


1  
UN408



# ARMORED MEDICAL RESEARCH LABORATORY

FORT KNOX, KENTUCKY

INDEXED

PROJECT NO. 3 - TOXIC GASES IN ARMORED VEHICLES

Supplemental Report On

Sub-Project No. 3-12 - The Carbon Monoxide Hazard from Auxiliary  
Generators in Tanks

ARMY  
MEDICAL  
MAY 27 1946  
LIBRARY

Project No. 3-12

INFORMATION COPY

April 2, 1943







ARMORED FORCE MEDICAL RESEARCH LABORATORY  
Fort Knox, Kentucky

Project No. 3-12  
File No. 723.13-1 GNOML

April 2, 1943

Supplemental Report On

CARBON MONOXIDE HAZARD FROM AUXILIARY GENERATORS IN TANKS

1. PROJECT: No. 3-12, Determination of the Carbon Monoxide Hazard from Auxiliary Generators in Tanks.

a. Authority - Letter Commanding General, Headquarters Armored Force, Fort Knox, Kentucky, 400.112/6 GNOHD, dated September 24, 1942.

b. Purpose - To determine the magnitude of the carbon monoxide hazard resulting from operation of auxiliary generators in tanks when the tank motor is not running.

2. DISCUSSION:

a. Methods. This report is a supplement to the report on M4 medium tanks, dated December 20, 1942, and covers the findings on three additional tanks: the M4A4, the M5A1 and the M7.

b. Carbon monoxide concentrations were determined at three points inside the tank during operation of the auxiliary generator: at an opening in the bulkhead and at the breathing zones of the loader and driver. In each case the tank was located in an open yard and oriented so as to provide a tail wind. The tank was buttoned up and the engine not running.

c. All tests were made without modifications in the location of the exhaust line from the auxiliary generator.

3. CONCLUSIONS:

a. Diffusion of carbon monoxide throughout the fighting compartment occurs rapidly so that the concentration in the bow is only slightly lower than in the turret.

b. M4A4.

(1) Operation of the auxiliary generator in the M4A4 tank when the tank engine is not running produces hazardous concentrations of carbon monoxide in the fighting compartment. (Fig. 1)

c. M5A1 and M7.

(1) The carbon monoxide concentrations found in the fighting compartments of these tanks, in the present tests, could be tolerated without danger for from one-half to one hour. The data indicate that a potential hazard exists. (Figs. 2 and 3)



1. The first part of the report deals with the general situation of the country and the progress of the work done during the year.

2. The second part of the report deals with the results of the work done during the year and the progress of the work done during the year.

3. The third part of the report deals with the results of the work done during the year and the progress of the work done during the year.

4. The fourth part of the report deals with the results of the work done during the year and the progress of the work done during the year.

5. The fifth part of the report deals with the results of the work done during the year and the progress of the work done during the year.

6. The sixth part of the report deals with the results of the work done during the year and the progress of the work done during the year.

7. The seventh part of the report deals with the results of the work done during the year and the progress of the work done during the year.

8. The eighth part of the report deals with the results of the work done during the year and the progress of the work done during the year.

9. The ninth part of the report deals with the results of the work done during the year and the progress of the work done during the year.

10. The tenth part of the report deals with the results of the work done during the year and the progress of the work done during the year.



4. RECOMMENDATIONS:

a. Extend the exhaust pipe from the auxiliary generator in the M4A4, M5A1 and M7 tanks so as to discharge beyond the rear wall of the engine compartment, in accordance with the recommendations of the report dated December 20, 1942.

b. Construction and maintenance of the exhaust line should be adequate to prevent direct leakage of exhaust gases into the fighting compartment.

c. Whenever possible, the hatches should be open during operation of the auxiliary generator with the tank motor not running.

Submitted by:

Capt. Norton Nelson, Sn-C  
Mr. Sgt. T. C. Swigert

APPROVED

*Willard Machle*

WILLARD MACHLE

Lt. Col., Medical Corps,  
Commanding.

3 Incls.

#1 - Fig. 1

#2 - Fig. 2

#3 - Fig. 3



10-11-12  
10-12-13  
10-13-14  
10-14-15  
10-15-16

10-16-17  
10-17-18  
10-18-19  
10-19-20  
10-20-21

10-21-22  
10-22-23  
10-23-24  
10-24-25  
10-25-26


10-26-27  
10-27-28  
10-28-29  
10-29-30  
10-30-31

10-31-32  
10-32-33  
10-33-34  
10-34-35  
10-35-36

10-36-37  
10-37-38  
10-38-39  
10-39-40  
10-40-41


10-41-42  
10-42-43  
10-43-44  
10-44-45  
10-45-46










1000  
 900  
 800  
 700  
 600  
 500  
 400  
 300  
 200  
 100  
 0





REVENUE  
 EXPENSES  
 PROFIT





1000  
 900  
 800  
 700  
 600  
 500  
 400  
 300  
 200  
 100  
 0



REVENUE  
 EXPENSES  
 PROFIT









MSAI

FIG. 2









#### LEGEND

- CO AS INDICATED
- CO AT LOADER POSITION
- - - CO AT DRIVERS POSITION
- - - - - AUXILIARY GENERATOR STARTED
- > HATCHES CLOSED

M7

FIG. 3





100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100